Work Order ID	5906
Tuesday, May 25, 2010	2:36:47

Quality Control



Page 1

Tuesday, May 25	5, 2010 2:36:47 PM			II						,g. ,
Item ID: Revision ID:	D3876-9		Accept				s	etup Star		
Item Name:	Protector - RH Aft Wall							Stop		
Start Date: Required Date: Reference:	5/25/2010 Start Qty: 2.00 5/31/2010 Req'd Qty: 2.00			Cust Item I Customer:	D:				110011101	
Approvals:	Process Plan:	Date://3525			nte:	_	R	un Star Stop		
	QC:	Date:	_ SPC (Y/N):	Da	ıte:			Stop		
Sequence ID/ Work Center II	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr		-					**		***
100			0.00							
	FLOW WATER JET						<b>4</b> 5.4	0-6-	7	
Waterjet	Memo		0.00					<u>6 -6</u>	L	
FLOW CNC Waterje	Dwg Rev Prog Rev	per Dwg D3876	SB	(0/06/08			Ø		C	Ð
	QC2- Inspect parts of	f machine FAI/FAIB	0.00				•		•	
QC Quality Control	Мето		0.00					10-6-7		
120	QC8- Inspect parts - s	second check	0.00	المدارم			<i>(</i> 2)			
QC	Mama		000	106107			$ \Theta$	<u></u>		<del></del>

W/O:			W	ORK ORDER CHANG	SES				,
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Da	ate Qty	Approval• Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:	Fault Cat	egory:	NCR: Ye	es No	DQA:	_ Date: _	
	Re	esolution:	Dispositi	on:	QA: N/C	Closed	d:	Date:	
NCR:			WORK ORI	DER NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC Section A	Description of NC Section A  Corrective Action Initial Chief Eng Chief Eng Corrective Action Action Description Chief Eng			n &	<b>/erification</b> Section C	Approval Chief Eng	Approval QC Inspector
				Office Ling					
					·				<b></b>

#### Work Order ID 59061

Tuesday, May 25, 2010 2:36:47 PM



Page 2

Item ID:

D3876-9

Accept

Setup Start

Stop

**Revision ID:** 

Item Name:

Protector - RH Aft Wall

**Start Date:** 

5/25/2010

Start Qty: 2.00

**Required Date: 5/31/2010** 

Req'd Qty: 2.00

**Cust Item ID: Customer:** 

Reference:

Approvals:

Process Plan: \_\_\_\_\_ Date: \_\_\_\_

Date:\_\_\_\_\_

**Tooling:** 

SPC (Y/N):

Date:

Run

Start

Stop

Sequence ID/ **Work Center ID** 

130

Packaging

Operation Description

Identify as per dwg & Stock Location:

Set Up/ **Run Hours** 

0.00

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

Packaging

Memo

0.00

59068

Date:

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/06/09 Af

W/O.	<del></del>		· · · · · · · · · · · · · · · · · · ·	DI ODDED OUTING						
W/O:			WC	RK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval* Chief Eng / Prod Mgr	Approval QC Inspector
					-					
						t			·	
Port No		DAD #	<b>5</b>					_		
Part NO		PAR #:								
		olution:							Date:	
NCR:			WORK ORDE	ER NON-CONFORMA	ANCE	(NCR	)			
DATE	STEP Description of NC			Corrective Action Secti	on B		Verific	rification Appro	Approval	Approval
	0,2,	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
					Ì					
									1	•
-						,				<u> </u>
							1			

#### **Picklist Print**

Tuesday, May 25, 2010 2:36:53 PM

Work Order ID: 59061

D3876-9 Parent Item:

Parent Item Name: Protector - RH Aft Wall

Comments:

IPP Rev:A 09-01-14 new issue DD verifyed by:EC

**Start Date: 5/25/2010** 

Required Date: 5/31/2010

Page 1

Start Qty: 2.00 Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MLEXS.125-F60029-04		Purchased	No			100	sf	1,769.706	3.14	6.610526			
										0.010320	KRII)~	6-7	

GE PLASTICS LEXAN SHEET

Location Loc Qty Loc Code MAT 1769.7068 111710 64 112585 173.383 114032 1532.3238

11400





W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval ' Chief Eng / Prod Mgr	Approval QC Inspector
	:								
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No <b>DQ</b>	A:	_ Date: _	
Resolution:									
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR	)			· · · · · · · · · · · · · · · · · · ·
DATE	STEP	Description of NC				Verific	fication	Approval	Approval
	0121	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
							ļ		
				. •				4	
			,						

DART AEROSPACE LTD	Work Order: 59	SUL
Description: Protector – RH Aft Wall	Part Number: D3	876-9
Inspection Dwg: D3876 Rev: A	Pag	e 1 of 1


spection Dwg: [	D3876 <b>Rev</b> : A	4				Pag	e 1 of 1
	FIRST	ARTICLE IN	ISPECTION	ON CHE	CKLIST		
	X	First Artic	cle	Proto	type		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Com	ments .
1.00	+/-0.030	(.00	*			······································	
24.25	+/-0.030	24.75	×				
16.98	+/-0.030	16,98	ي				
17.77	+/-0.030	17.71	>-				
11.85	+/-0.030	11.85	7				
10.44	+/-0.030	10.44	علا				
0.125	+/-0.010	,(33	৮				
					·		
·							
							•
							-
	•						
easured by:		Audited by:			Prototype Appi	roval:	N/A
	0-12	Date	0 1 1			Data	N/A


Meas	Measured by: K		Audited by:	5	Prototype Approval:	N/A
	Date:	10-67	Date:	10/06/07	Date:	N/A
Rev	Date	Change			Revised by	Approved
A	09.06.22	New Issue			KJ 🐪	ZX.








D. D 18.55 2.76 R0.75 0.125 2 PL REF R2.13 2 PL D3876-5 PROTECTOR - LH WALL (TEXTURED SIDE SHOWN) NOTES: 1) MATERIAL: F60029-GY3778 GREY LEXAN SHEET (HEAVY HAIRCELL TEXTURE) 0.125 THICK REF DART SPEC MLEXS.125-F60029-04 DESIGN DART AEROSPACE LTD 2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: IDENTIFY WITH DART P/N "D3876-5" AND B/N USING FINE POINT PERMANENT INK MARKER ON SMOOTH SIDE
7) WEIGHT: 8.07 Ibs
8) CHECK PER TEMPLATE DT8926 DRAWN HAWKESBURY, ONTARIO, CANADA CHECKED DRAWING NO. REV. A D3876 MFG. APPR. SHEET 3 OF 7 APPROVED TITLE SCALE BAGGAGE PROTECTOR DE APPR. NTS COPYRIGHT © 2009 BY DART AEROSPACE LTD.
IT IS PRIMATE AND COMPREHEN, AND IS SUPPLIED ON THE EMPRESS CONDITION OF THE MEAN OF T DATE 09.04.02












W/O:			V	ORK ORDER CHANG	ES			-		<u> )</u>		
DATE	STEP	PRO	CEDURE CH	ANGE	В	у	Date G	Qty	Approval Chief Eng / Prod Mgr	Approval QC1nspector		
<del></del>												
		·										
Part No	•	PAR #:	Fault Cat	tegory:	_ NCR: `	res N	o DQA:_	-	Date:			
				Disposition: QA: N/C Closed: Date:								
NCR:		V	VORK ORI	DER NON-CONFORMA	NCE (I	ICR)						
DATE	STEP	Description of NC		on B			on	Approval	Approval			
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section C		Section C		Chief Eng	QC Inspector
								:				
							:					
									••			
										·		
	1		1 1		ı		Į.	ı		•		



W/O:		WORK ORDER CHANGES												
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	:	PAR #:	Fault Categ	Jory:	NC	R: Yes	No <b>DQ</b>	A:	Date: _					
	Re	esolution:	Disposition	1:	QA	QA: N/C Closed: Date:								
NCR:			WORK ORDE	R NON-CONFO	RMANCE	(NCR	)							
DATE	STEP	Description of NC		Corrective Action	Section B		Verifi	cation	Approval	Approval				
	0,2,	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date			Chief Eng	QC Inspector				
		·												
NOTE: D	ate & initia	al all entries			<del></del>	<u> </u>				I				

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE